## **COAL AGE**

With Which is Consolidated The Colliery Engineer

## INDEX TO VOLUME XIV

July 1 to December 31, 1918

EXPLANATORY NOTE	Page	
Note—Illustrated articles are denoted by an asterisk (*), book notices by a dagger (†) Titles are often abbreviated. They are indexed under their most important words, or, if no	Axle straightening 535 Axles, heat treated. Pearson 315 Axles, Mine-car, Lieberman 219	British Columbia Coal mining. Dunn 56
word be distinctive, under their first one (except "A," "The," etc.), or under some topical word not found in the title. Authors', geographical and other proper names are also used freely.	В	Brooks, L. W. Waterproof plunger grease 261 Broughton, H. J. Coal, explosives, war *158, *214, *258
Following is a list of the pages included in the several numbers of the volume, by date:  July 6	Back to the mines. Strohm	Brown, C. J. Reliable gears
July 27     155-200       Aug. 1     201-248       Aug. 8     249-296       Aug. 15     297-349       Aug. 20     341-384       Aug. 29     385-426       Sept. 5     427-476	ends	Bullock, O. The mining situation 234, Hindrances to coal production 462, Load- ing coal at the face 658. Miner and his pleasure 796. Wagon mine a menace 834, Calculating a room switch1087
Sept. 12.         " 477- 532           Sept. 19.         " 533- 578           Sept. 26.         " 579- 624           Oct. 3.         " 625- 672           Oct. 10.         " 673- 720           Oct. 17.         " 721- 766           Oct. 24.         " 767- 806	cating tools on nervous system	BUREAU OF MINES  —Analyses of mine and mine car samples 396  —Coal-tar products
Oct.       31.       " 807- 845         Nov.       " 846- 888         Nov.       1.       " 889- 928         Nov.       21.       " 929- 970	Bell Alarm, on mine car. Stafford	—Report, yearly
Nov. 21     929-970       Nov. 28     971-1014       Dec. 5     1015-1058       Dec. 12     1059-1102       Dec. 19     1103-1146       Dec. 26     1147-1188	Belts, Putting on heavy •1105  Bessemer Coal & Coke Co.—Village layout.  Miller •130  Bibliography machine loading. Engel. •974  Bier, J. A. Mine-car door. •141  Einding timbers on a truck. Rice. •48	Buried under rock and yet lives. Graham 403 Burns, Treatment of, with wax
A	Bituminous loaded at Lake Eric docks. 814, 987 Bituminous prices fixed. Garnsey, Norris	Business as usual
Abjure the word not	and Allport 685 Bituminous reduction, New England. 950 Bituminous storage authorized, increased. 785 Bituminous supplants anthracite 225 Bituminous under steam boilers 266 Bituminous used in 1917 and 1918 360	с •
Accidents, British mine	Bituminous, use of Illinois and Indiana.     865       Blackdamp on pitches. (inq.)     568, Discussion       530     753       Blacken bolt heads     580       Blacksmith shop, fireproof     812	Caging saves labor, Automatic. Brown. 257 Cahen, A. J. Crosshead removed by heat- ing *428, Replacing a belt
Accidents, Missouri. (Note)	Blagg, E. (Poster)	presers 211 Callen, A. C. Determination of latitude and meridian 168 Calloway, R. J. Safety on electric hoist. 478 Cambria Steel Co.—Hinckston Run mine.
Accounting of materials 417, Discussion.  *755, 956  Accusation that does not asperse1041	BLASTING  —Blasting with lightning circuit. Pascoe.*342  —Blasting ditch in mine. (inq.) *1128, Discussion	Cameron, W. H. (Photo)
Affelder. W. L. Hecla Co. gives service medal         *228           Air-cylinder lubrication. (inq.)         522, Discussion           836, 1132         836, 1132           Air, Excess. and heat efficiency         585           Air trap, effective         *343	-Detonators, Handling electric. Discussion 80 -Explosives in mining, Permissible. Discussion 518 -Explosives, Safety in use of La Motte 490 -Firing wet holes. Price	Canada. western, coal supply. (Notes) 147, 617 Canadian Western Fuel Co.—Cage accident 617, 729, Working thick coal. Stafford. *890 Canal, New York Barge, coal transportation. Discussion. 835
Air trap, effective "343 Alabama, coal production 178, 663 Alabama prices 406, 866 Alarm to show fan trouble Decker 972 Alaska, coal mining (Notes) 378, 571.	Fuse tester. Lauther *298  Liquid oxygen explosives 540  Priming a cartridge. Discussion *327, 521  - Priming a cartridge *1111  Shotfring in mines. Discussion 234, 327	Discussion 835 Canal route for Illinois coal 73 Cantilevers. Steel, support headframe 553 Carbon Hill Coal Co.—Plant at Carbonado. Jarrett 988
Alaskan engineering, special commission. 785 Allport, J. H. Prices bituminous coal. 685, 736 Amenities in mine villages. Fuetter 496	—Shotfiring in mines. Discussion	Jarrett
Amer. Inst. of Mg. Engrs.—Colorado meeting 351, Paper	Blue gem coal in Tenn. (inq.) 80, Discussion       189         Boiler scale prevention       1163         Boiler tubes. (Photo)       675	Car shortage. (Notes) 37, 147, 276, 289, 377, 419, 468, 713, 799, 839, 880 Car trips returning to mine. (Photo) 312 Cars, coal, more loaded this year
American vs. British ideals. 138 Analysis.—Character South Wales coals. 751 Analysis of power consumption. •777 Analyzed. Coal. Serviss	Boilers—Coxe stokers *676 Boilers, Fans and Owens 937 Boilers, Raising two 350 hp. Scheble. *392 Boilers, Steam, at coal mines (inq.). 1179 Boilers—Waste gases for steam generation.	Cars. Cost of upkeep of mine. (inq.) 918, Discussion
and safeguards in. Glover. 901 Anthracite costs, New schedule. 905 Anthracite from lake docks. 275 Anthracite fuel made by hand. 450 Anthracite, Loss in storage. (inq., 330	Kershaw 591 Bonding and welding Huber 100 Bonuses, Kentuckian advocates 559, 561 Book reviews 223 Bounce condition. Unusual Watts 1028	Cars loaded, 1918 999, *1045, 1174 Cars, Railroads should deliver clean 1172 Cars, roller bearing mine. Porter . *122 Carruth, C. W. Calculating a room switch 1088 Cartoons
Anthracite mine cave situation. 598 Anthracite. Scraper mining of thin bed. Humphrey	Bow Dougherty's ghost	Cartoons
Anthracite stripping .57 Anthracite coal stripping Kennedy .644 Anthracite To increase production .997 Appleton J. Specializing in the mine .109 Apply your thought. Hodges .49 Arnatures Winding (inq.) .137	ery and supplies 782 Bradley, J. G. Sketch; portrait. 404 Braley, B. Responsibility *354, The coal army *540, *Straight stuff. *625 Brantley coal cutter . *596 Brazil, Fuel problem . 1160	Cement gun in bituminous mine. Sloman. *1158 Cement gun, Relined a mine shaft with. *400 Cement work, Waterproofing. (inq.). 1092 Central Penn. Coal Producers' Assn.— Record bulletin
Apply your thought. Hodges. 49 Armatures. Winding (inq.)	Brazil. Fuel problem	Record bulletin
Auburn & Alton Coal Co.'s record run	Brick and concrete work Novel *780	Chance acetylene safety lamp.       *824         Chappelle, C. W. Advantages storage-battery locomotives *437, Discussion.       439         Character South Wales coals       751         Charcoal prices       68         Chart of chimney losses       268

## **COAL AGE**

With Which is Consolidated The Colliery Engineer

## INDEX TO VOLUME XIV

July 1 to December 31, 1918

EXPLANATORY NOTE	Page	
Note—Illustrated articles are denoted by an asterisk (*), book notices by a dagger (†) Titles are often abbreviated. They are indexed under their most important words, or, if no	Axle straightening 535 Axles, heat treated. Pearson 315 Axles, Mine-car, Lieberman 219	British Columbia Coal mining. Dunn 56
word be distinctive, under their first one (except "A," "The," etc.), or under some topical word not found in the title. Authors', geographical and other proper names are also used freely.	В	Brooks, L. W. Waterproof plunger grease 261 Broughton, H. J. Coal, explosives, war *158, *214, *258
Following is a list of the pages included in the several numbers of the volume, by date:  July 6	Back to the mines. Strohm	Brown, C. J. Reliable gears
July 27     155-200       Aug. 1     201-248       Aug. 8     249-296       Aug. 15     297-349       Aug. 20     341-384       Aug. 29     385-426       Sept. 5     427-476	ends	Bullock, O. The mining situation 234, Hindrances to coal production 462, Load- ing coal at the face 658. Miner and his pleasure 796. Wagon mine a menace 834, Calculating a room switch1087
Sept. 12.         " 477- 532           Sept. 19.         " 533- 578           Sept. 26.         " 579- 624           Oct. 3.         " 625- 672           Oct. 10.         " 673- 720           Oct. 17.         " 721- 766           Oct. 24.         " 767- 806	cating tools on nervous system	BUREAU OF MINES  —Analyses of mine and mine car samples 396  —Coal-tar products
Oct.       31.       " 807- 845         Nov.       " 846- 888         Nov.       1.       " 889- 928         Nov.       21.       " 929- 970	Bell Alarm, on mine car. Stafford	—Report, yearly
Nov. 21     929-970       Nov. 28     971-1014       Dec. 5     1015-1058       Dec. 12     1059-1102       Dec. 19     1103-1146       Dec. 26     1147-1188	Belts, Putting on heavy •1105  Bessemer Coal & Coke Co.—Village layout.  Miller •130  Bibliography machine loading. Engel. •974  Bier, J. A. Mine-car door. •141  Einding timbers on a truck. Rice. •48	Buried under rock and yet lives. Graham 403 Burns, Treatment of, with wax
A	Bituminous loaded at Lake Eric docks. 814, 987 Bituminous prices fixed. Garnsey, Norris	Business as usual
Abjure the word not	and Allport 685 Bituminous reduction, New England. 950 Bituminous storage authorized, increased. 785 Bituminous supplants anthracite 225 Bituminous under steam boilers 266 Bituminous used in 1917 and 1918 360	с •
Accidents, British mine	Bituminous, use of Illinois and Indiana.     865       Blackdamp on pitches. (inq.)     568, Discussion       530     753       Blacken bolt heads     580       Blacksmith shop, fireproof     812	Caging saves labor, Automatic. Brown. 257 Cahen, A. J. Crosshead removed by heat- ing *428, Replacing a belt
Accidents, Missouri. (Note)	Blagg, E. (Poster)	presers 211 Callen, A. C. Determination of latitude and meridian 168 Calloway, R. J. Safety on electric hoist. 478 Cambria Steel Co.—Hinckston Run mine.
Accounting of materials 417, Discussion.  *755, 956  Accusation that does not asperse1041	BLASTING  —Blasting with lightning circuit. Pascoe.*342  —Blasting ditch in mine. (inq.) *1128, Discussion	Cameron, W. H. (Photo)
Affelder. W. L. Hecla Co. gives service medal         *228           Air-cylinder lubrication. (inq.)         522, Discussion           836, 1132         836, 1132           Air, Excess. and heat efficiency         585           Air trap, effective         *343	-Detonators, Handling electric. Discussion 80 -Explosives in mining, Permissible. Discussion 518 -Explosives, Safety in use of La Motte 490 -Firing wet holes. Price	Canada. western, coal supply. (Notes) 147, 617 Canadian Western Fuel Co.—Cage accident 617, 729, Working thick coal. Stafford. *890 Canal, New York Barge, coal transportation. Discussion. 835
Air trap, effective "343 Alabama, coal production 178, 663 Alabama prices 406, 866 Alarm to show fan trouble Decker 972 Alaska, coal mining (Notes) 378, 571.	Fuse tester. Lauther *298  Liquid oxygen explosives 540  Priming a cartridge. Discussion *327, 521  - Priming a cartridge *1111  Shotfring in mines. Discussion 234, 327	Discussion 835 Canal route for Illinois coal 73 Cantilevers. Steel, support headframe 553 Carbon Hill Coal Co.—Plant at Carbonado. Jarrett 988
Alaskan engineering, special commission. 785 Allport, J. H. Prices bituminous coal. 685, 736 Amenities in mine villages. Fuetter 496	—Shotfiring in mines. Discussion	Jarrett
Amer. Inst. of Mg. Engrs.—Colorado meeting 351, Paper	Blue gem coal in Tenn. (inq.) 80, Discussion       189         Boiler scale prevention       1163         Boiler tubes. (Photo)       675	Car shortage. (Notes) 37, 147, 276, 289, 377, 419, 468, 713, 799, 839, 880 Car trips returning to mine. (Photo) 312 Cars, coal, more loaded this year
American vs. British ideals. 138 Analysis.—Character South Wales coals. 751 Analysis of power consumption. •777 Analyzed. Coal. Serviss	Boilers—Coxe stokers *676 Boilers, Fans and Owens 937 Boilers, Raising two 350 hp. Scheble. *392 Boilers, Steam, at coal mines (inq.). 1179 Boilers—Waste gases for steam generation.	Cars. Cost of upkeep of mine. (inq.) 918, Discussion
and safeguards in. Glover. 901 Anthracite costs, New schedule. 905 Anthracite from lake docks. 275 Anthracite fuel made by hand. 450 Anthracite, Loss in storage. (inq., 330	Kershaw 591 Bonding and welding Huber 100 Bonuses, Kentuckian advocates 559, 561 Book reviews 223 Bounce condition. Unusual Watts 1028	Cars loaded, 1918 999, *1045, 1174 Cars, Railroads should deliver clean 1172 Cars, roller bearing mine. Porter . *122 Carruth, C. W. Calculating a room switch 1088 Cartoons
Anthracite mine cave situation. 598 Anthracite. Scraper mining of thin bed. Humphrey	Bow Dougherty's ghost	Cartoons
Anthracite stripping .57 Anthracite coal stripping Kennedy .644 Anthracite To increase production .997 Appleton J. Specializing in the mine .109 Apply your thought. Hodges .49 Arnatures Winding (inq.) .137	ery and supplies 782 Bradley, J. G. Sketch; portrait. 404 Braley, B. Responsibility *354, The coal army *540, *Straight stuff. *625 Brantley coal cutter . *596 Brazil, Fuel problem . 1160	Cement gun in bituminous mine. Sloman. *1158 Cement gun, Relined a mine shaft with. *400 Cement work, Waterproofing. (inq.). 1092 Central Penn. Coal Producers' Assn.— Record bulletin
Apply your thought. Hodges. 49 Armatures. Winding (inq.)	Brazil. Fuel problem	Record bulletin
Auburn & Alton Coal Co.'s record run	Brick and concrete work Novel *780	Chance acetylene safety lamp.       *824         Chappelle, C. W. Advantages storage-battery locomotives *437, Discussion.       439         Character South Wales coals       751         Charcoal prices       68         Chart of chimney losses       268

D	Poss	P
Chart—Working force at six mines 302 Charts, accident 486 Charts, accident 726 Charts, accident 726 Charts, accident 726 Charts, accident 726 Chering news from coal mines 726 Cheering news from coal mines 726 Cheering news from coal mines 185 Chesapeake & Ohio, statement 1014, Reduces car quota. (Note) 1053 Chicago, Wilmington & Franklin Coal Co. —Orient mine. Harris 344, 932. Largest day's output 934 Chips from eye, aid in removing. (Photo) 156 Chieal, The cold. Lucas. 730 Chocks, Mine car 973, 1101 Cleanliness, Corporational and personal 81 Clearfield Bituminous Coal Corp.—Keeping tabs on absentees 602 Coal Age—Index 113, 255. Ideas and Suggestions 115. Safety number 324 Coal allotments by U. S. Fuel Administration. (Note) 761 Coal and coke, U. S. 1917 647, 745 Coal are you burning? What 954 Coal deposits of world 909 Coal, explosives, war. Broughton 158, 214, 258 Coal dirty. (Poster) 183 Coal industry's strong position 971 Coal industry's spart in war. Cornwell 695 Coal Liberty 931 Coal may oust gasoline 1172 Coal may oust gasoline 1972 Coal Mg. Inst. of Amer.—Program 948, Papers *1021, 1025, *1060, *110. Meeting 1026 **110. Meeting 1026 **1110. Meeting 1026 **1111. Meeting 1026 **11110. Meeting 1026 **1111. Meeting 1026 **11111. Meeting 1026 **1111. Meeting 1026 ***11111. Meeting 1026 ***11111. Meeting 1026 ***11111. Meeting 1026 ***1111111. Meeting 102	Discussion	— Signal to indicate discontinuance of 1 oad. *723 — Storage battery locomotives. Chappelle
Coal problem under war conditions. Stock 393	De Mayo bunkering machines	tus. Huber*100 Estimating power in haulage (ing.) 615,
Coal recovery in Illinois	Delaware & Hudson Coal Co.—Stripping operation *57. Face conveyor. Davis *92	Discussion
Coal. Where the, we produce is consumed. 170 Coffin, F. H. Carbide vs. electric mine lamps	Derailing device, Simple. Powell 931 Derailments are notential casualties. 517	EXAMINATION QUESTIONS
COKE	Development period of a mine stock1076 Dewatering pits for washed coal•1072 Dickinson. W. Sealing on fire on intake	British Columbia, First classGases, ventilation 36Hoisting engineersBoilers, signaling,
—Breeze, coke. (Notes)	*187. Coal conveyors at face*450 Dinner pail cooler	etc., 418: engines, rope fastening.
Byproduct coking practice. Sperr 1068, *1114, *1156	Ind. coals. Traer	boiler practice
—Byproductless ovens waste coal, Where 174  —Byproducts, Recovery. Meredith 60  —Coke company to make large refund 557	Dock loadings. (Notes)       149, 195, 379, 619, 987, 1053, 1095, 1141         Dock—U. C. coaling plant. (Note)       39         Dog for lowering mine timbers       *386	after explosion, fire
-Coke making in New South Wales. 778 -Glazier, R. C., coke inspector. 557 -Innovation in coke industry Gans. 256	Dog for lowering mine timbers *386 Door, American mine	ventilation, doors, brattices, overcasts, splitting, instruments
-Must have larger coke output 699	Dog for lowering mine timbers   -350	explosives, accidents, gases, 146; squeeze, safety, timbering, safety
—Ovens idle 15 yrs, resume. (Note) 291 —Prices 68, 226, 275, 513, 573, 744, 1051 —Record production. (Note)	Drilling device. Lucas *891 Drilling, Diamond 856 Drilling, Diamond 856	lamps, haulage
—Screenings, coke, salvaging discontinued 617 —Shipments to be inspected. (Note) 524 —Tables of percentages and volatilization.1034	Drillings, Grit guard for overhead. Lucas. 299 Drilling with_the vise	<ul> <li>Misc.—Boilers, steam engines, hoisting. 879</li> <li>Misc.—Hoisting rope, ventilation, electricity, engines 838, Correction1050</li> </ul>
Cold weather instrument work	Drills, Little Giant*1166 Drink too much Do mine workers 458	-MiscPumping, gases, ventilation1180 -MiscVentilation, water gage, labor, mine fires919
Colorado, coal production, 1918, (Note). 72-5. Colorado Fuel & Iron Co.—War contribu- tions. (Note) 403. Girls' camp at Prim-	Drivers of yesterday and today 369 Dumper, double car 1122 Dump pivot, Finding, Price. 202 Dunn, R. Coal mining in British Columbia	-Misc.—Ventilation, priming, piping, boiler fittings, haulage, gases1005
ero *468 Community work 873	55, Revelopments of Granby Cons. Mfg. & Sm. Co. 224. Provincial rights dispute in	-Misc.—Ventilation, mine car, drainage, working, gas
Colorado, safety 1178 Combination tool, Useful 931 Combustion. (Notes) 98, 167, 170, 343, 351, 404, 447, 547, 555, 590, 597, 681, 987	Canada         *352           Duplex instruments         *597           Duty and destiny         429	doors, ventilation, blasting, explosives 466 —Pittsburg, Kans., mine foremen.—Gases, roof falls, ventilation, working, entry
Compensation. (Notes) 570, 662, 799, 963 1006, 1181	Duty and destiny	yardage, barometer, fans
Compressors, air. (Photos)	Е	doned mine, squeeze, water gage, tim- bering, explosion, anemometer, ven- tilation
Commutation service, miners want 367	Economic losses arising from high ash coal 830 Education and labor unrest 458	tilation
kinson	Education—financial and social barometer.	measurements, blasting, uses of ane- mometer water gage, thermometer and barometer, supplies, miners' qualifica-
Concrete, Effect of salt on reinforced. 991 Concrete foundations, Springer. *204 Concrete houses, investigation 779 Concrete, Reinforced, pit props, Meredith 362 Concrete work, Novel brick and 780	Effect pneumatic reciprocating tools.  Barnes	barometer, supplies, miners' qualifica- tions and tools, 661; safety laws, safety mine examination, 712; ventila- tion open lights, safety laws, ex-
	Efficiency, Greater or lower wages	tion, open lights, safety lamps, explosions, duties of fireboss
Condenser, acid resisting	*724, *773, *820, *857, *903 Efficiency in firebossing. Discussion1133	safety lamps, maps, safety, timbering 238  Exemption for coal miners. Discussion 709
Connor, C. H. Standardization of first-aid methods 728	ELECTRICITY. See also "Haulage," "Power," "Locomotive,"	Exline, R. Waste of coal1176
Connellsville Basin Coke Co. (Photo) 134 Conservation of miners. Herrick*162 Conservation section of R. R. administration 363	"Lamp." —Alternating-current motor trouble 931	EXPLOSION. See also "Dust," "Gases, Mine," "Ventilation."  —Boiler explosions (inq.)
Conserve mine material 453 Conserving coal 134 Consolidation Coal Co. 65, *1148 Constitution practice in mining Disagraph 135	-Armatures, Winding (inq.)	—Boiler explosions (inq.)
Consumers' Mfg. Co. development 684	—Circuit breakers, Automatic	Explosives, Conservation. Jones
Consumption, bituminous	—Direct-current armature trouble. Hus- kinson	cussion 518 Explosives, Liquid oxygen 540 Explosives, Safety in use of La Motte 490 Exports See "Trade."
Contracts may cover longer period 275 Conversation between two cars of coal. 126 Conveyor from mine to tipple. 129	—Distribution system of Lehigh C. & N. Co. *850	Exports. See "Trade." Eye hazard in coal mining
	—Duplex instruments	F
cussion	—Hoist, Safety on electric. Calloway*478	Face coal shoveler and loader (inq.)*711 Fairmont, W. Va., operators, (Photo) 229
Conveyors replace common labor	*820, *857	Fan. See "Ventilation." Fanhouse, Lehigh Valley Coal Co
		Farrington opposed bonuses 322, Sidesteps prohibition
Corporational and personal cleanliness 831	-Motor stop. Water indicator and. Hus-	Fay, A. H. Careful records reduce mine
Cost sheet, A uniform	kinson	accidents 113853. 503

Federal Trade Comm.—Report, 21; arraignment of, 513; To investigate cost of anthracite. (Note)	Page   Page	Humphrey, E. P. Scraper mining of thin bed anthracite
G	-Motor, mine. Wheeler*1167	907 Discussion 463
Gans, J. L. Innovation in coke industry 256 Garcia, J. A. Sketch; portrait. 360 Garfield letter to Conciliation Board. 367 Garnsey, C. Prices bituminous coal. 685, 736 Gases, Molecular consistency 401 Gas coal in northwest 198 Gasification of coal. Meredith 982 Gas, coal. Meredith 982 Gas, coal. Meredith 1071 Gas, power, Advantages of using. Meredith 689 Gas, Power of coals and. Owens. 312 Gas wells, Abandoned 1113 GASES, MINE  —Blackdamp on pitches (inq.) 568, Discussion 753 —Diffusion of gases (inq.) 145 —Explosive gases in coal. Ashworth 993 —Methane as a fuel. Williams 988 —Outbursts of gas in Crowsnest field. Ashworth 988 —Outbursts of gas in Crowsnest field. Ashworth 983 Gay Coal & Coke Co.—Semi-monthly bulletin 740 Gear puller (Photo) 157 Gears, Reliable, Brown 99 Gelston, J. S. Mine-rescue work 324 Generation of electrical energy 697 Geological Survey—Peat deposits, 115, 226. Eltuminous consumption, 170: Peat as fuel, 734; Coal and coke, 1917, 745; Minerals produced 1917, 1168; Lake shipments 1169 Geology—Bounce condition. Watts, 1028 German pre-war and present coal prices 642 Getting a bit of their own back 940 Gibbons' Cardinal, letter to Dr. Garfield, 451 Gibbs apparatus 1129 Glover, D. K. Hazards and safeguards in anthracite breakers 901 Gondolas, steel, used as armored cars, (Photo) 756 Discussion 959 Graham, E. H. Buried under rock and yet lives 959 Grabam, W. J. Travel of electric current 232. Peversing electric motor 1044 Graphite 911, 1133 Gray, H. E. Testing for gas in mines *217.	—Locomotives. Hauling capacity. Discus-	Intemperance hampers production. Hall
Grease cup filler. Schwartz	-Shaft problems (inq.) 1049 -Single-drum, room hoist 120 -Surface plant at Orient mine 932 -Holland to get American coal 827, 865 -Homografe, fuel	Klebba, L. Michaelson briquetting machine *596 Kneeland, F. H. Partners with the Kaiser 579, Annual meeting of Coal Mg. Inst. of Amer
mining. *564 Greece, Lignite. 1165 Grit guard for overhead drillings. Lucas. *299 Gulliver. J. high daily production. 649	Homemade fuel	L
H	Hosovo, G. Improved coal equipment. 465 House scarcity. 871 Houses, concrete, investigation. 779 Houses, Madison Coal Corp. *7	LABOR  -Agreement, Fairmont, W. Va
Hacksaw and cross peen hammer	Houses, Madison Coal Corp. *7  Housing in the mining regions 137, (Notes) 193  Howard, F. K. Mining equipment. 913  Howard, J. loads 50 tons in one day. *747  Huber, W. E. Bonding and welding apparatus. *100  Hughes, T. O. Electric mine haulage. 233	Agreement, Fairmont, W. Va
mining torrest.		The same of the sa

Domo	To me	Dage
LABOR—Continued  —Awards, National, for steady work. 650  —Bonus nu.sance to be ended. 278, 365  —Bureau of labor. 287  —Canadian coal miners must work or fight 182  Corporal in every squad of eight. 608  —Crowder, Gen., drafting miners. 276  —Butes of eserciay and today. 369  —Education and labor unrest. 458  —Education. Virgin. 447  —Einect of war on labor. 1173  —Efficiency in firebossing. Discussion. 1133  —Employment service, U. S. 25  —Exemption of coal miners. Discussion. 709  —Exemption of Coal miners. 232, 25  —Foreign-born miners, Loyalty of. Discussion. 709  —Exemption of coal miners. 189  —Hecla Co. gives service medal. Affelder. 228  —Increase demanded in northern anthracite fields. 322  —Intemperate men cause tonnage losses. 302  —Investigations board. 181  —Is it the miner or system? 768  —Justice to the miner. Discussion 413  —Labor-adjusting agencies, statement. 829  —Labor will remain under Fuel Administrator's jurisdiction. 228  —Lord, J. charge of labor for mines. 277  —Man power and longwall mining. 564  —Marn power. Coal mining and. Pocock. 350, Discussion. 564  —Marn powers. (Note). 1183	Lehigh Valley Coal Co.—Redivision of districts 289, Fire in William A. Coll. 289, Fourth Liberty Loan	Meridian, Determination of latitude and Callen
Mexicans in anthracite field. (Note)378Mine foreman, get in touch with your185Miner and his pleasure. Discussion 329,Miner as a casual worker368Miners oppose ending of apprenticeship608	Loading coal, methods and appliances, Engel. 974 Loading equipment, Mackie. 120 Loading, Hampton Roads. 1027 Loading Lake Erie docks. 814 Loading with electric shovels, Brennan, 1018	Nail, upturned.       (Photo)       177         Nails, driving.       (Photo)       675         National Retail Coal Merchants' Assn.       964         National Safety       Council—History 484. Papers 490, 503, 310, 728, 901, 1118, Meeting       502, 302, 303, 303, 303, 303, 303, 303, 3
-Miners work Sundays to offset influenza loss	Loadings show increase over 1917 907 Locating coal beyond a fault. (inq.) *797. Discussion 915, *1088 Locker arrangement 534 Locomotives, Advantages of storage-battery. Chappelle. *437. Discussion *439 Locomotive, storage-battery, Ashmead *548 Locomotives, Hauling capacity of. Discussion 958 Locomotives, Hauling capacity of. Discussion 958 Locomotives, Hauling capacity of. Discussion 958 Locomotives, and trucks. Electric 387 Locomotives Exhaust of gasoline. (inq.) 375 Locomotives—Gathering attachment 121 Locomotives—Gathering attachment 121 Locomotives, three types 836. 1132 Lubrication, Air-cylinder. (inq.) 522, Discussion 836. 1132 Lubrication, Coal production and. Trautschold 175 Lubrication of air compressors. Callan 211 Lueas, A. Grit guard for overhead drillings *299, Old man fastening *387, Removing a tight crank pin *428. Positive grip for oil cans *723. The cold chisel *730, Special drillings device *891, Tip	Neale, J. B
-Shortage of mine labor. Discussion. 79, 186 -Situation. 23, 69, 135, 180, 227, 276, 321, 365, 407, 455, 511, 558, 605, 650, 701, 746, 787, 828, 867, 908, 951, 995, 1040, 1127, 1170 -Situation, mining. DiscussionSlacker on record	*730. Special drilling device *891, Tip for ink bottle *930. Lucky thirteen. Strohm *935. Luxton, W. H. Locating coal beyond a fault *1088. Lyons, J. Testing a breathing apparatus *1019	North Western Mining & Exchange Co.— System of mining *266, Brick and con- crete work
Untrained men will not serve our ends. 609Wage adjustment. Discussion	McDowell Coal Co.—(Photos.)	Nut, locking. (Photo)
—Wage scale, Missouri.       25         —Wages adjusted to living costs.       457         —Wages, Greater efficiency or lower.       1042         —Wages in Silesia.       1040         —Wages, Shamokin district.       995         —Want pay for what others endured.       705         —Waste, coal.       Discussion.       1176         —When John no longer defers to you.       705	ment. *120 Madiera-Hill Coal Co.—Automatic tipple switch. Price. *250 Madison Coal Corp.—Mine No. 6 *4, Automatic deflector *92. Portable saw. *93 Magazines. *1111 Magraw R M Increased production in	Oblique faced rooms. Sutherland. *580
Working hours	war-time. 635 Maize, R. Ventilating a gassy slope mine 565. Use and location of booster fans. 659 Mandel, E. L. Keeping track of miners' safety. 93 Map. Fairmont, W. Va. 1150	Old man fastening. Lucas*387
LAMP, MINERS'  —Acetylene and electric cap lamps, Chance. 1118 —Acetylene safety lamp, Chance. *824 —Carbide vs. electric. Discussion. 30 La Salle County Carbon Coal Co.—Longwall mining. Harris. *388, Machine mining.  Harris. *536	Map. No. 6 mine, Madison Coal Corp. 9	cement gun. *400 On center and backfired . 552 On your work their health depends (Poster) . 1043 One-industry nation. 324 Operator's attitude to workingman . 750 Operators contradict McAdoo . 556 Orient mine. Harris
	Maps. mine.  Maps.—Percentage of grade. (inq.) *756, Discussion.  959 Marcus screen. Miller.  Marshall. R. A. Ventilating a gassy slope mine 914. Highrances to coal production	Our great-hearted coal miners. Flexner *498 Output be increased scientifically. Joyce . 356 Output is consumed. How our
-Interpreting mining laws. Discussion 33, 77, 143 -Legal decisions 62, 213, 318, 357, 396, 436, 544, 604, 649, 694, 727, 784,	1003. Miner and safety.  Martin. C. Plant of Conemaugh Smokeless Coal Co.  419  Mathressen & Hegeler Zinc Co.—Alarm.	P
S25, 907, 948, 965, 981, 1030, 1124, 1162 Lawrence, J. Selecting mine foremen	Maximum production for humanity's sake. Porter.  May we show the warriors a seat?	Pacific Coast Coal Co.—Explosion (Note). *525 Paint, weather resistant
1		

Page	Page	Page
Peabody coal development in central Illi- nois. Harris	Production, anthracite, increase 997	SAFETY—Continued —Accidents, Mine. Jarrett
Peabody, F. S. Government control1112	Production, 1917, U. S., 647, 745; first half 1918	-Alarm bell on car. Stafford429
Peace and waste are not synonymous 954 Peale, R. resigns	Production bureau to cooperate with mine	—Appliances in warfare. Trego
Pearson, E. A. Heat treatment of axle steel	Production committee 275, Managers 363	-Constructive practice in mining. Discus-
232, Advantages of heat treatment 315 Peat as fuel 734	Production, France since 1913 900 Production, Hindrances to coal. Discussion	sion
Peat as fuel	462, 612, 710, 795, 873, 1003, 1044, 1087	—Deflectors, automatic
Peat deposits of United States	462, 612, 710, 795, 873, 1003, 1044, 1087 Production Intemperance hampers. Hall.	—Derailments are potential casualties 317
Peat fuel, Would replace coal by 819	297, Discussion	—Electric hoist, Safety on. Calloway*478 —Explosives, Safety in use. La Motte 490
Peat industry breaks records	Production manager, Coal industry's 953 Production, Novel scheme for boosting*361	—Fails on roadways. (Poster) 955 —First-aid to the uninjured. Discussion. 283
Peele's mining engineer's handbook	Production quotas assigned 744	-Handling electric detonators. (inq.) 80
Penn. Coal Co.—(Photos) 64. Production	Production quotas assigned	<ul> <li>Importance of spreading safety work 790</li> <li>Keeping track of miners' safety. Mandel. 93</li> </ul>
notes	Progress, Don't apostrophize	-Lamps from a safety standpoint. Chance1118
Penn., coal production. (Notes) 37	Prop. jack, Quickly adjusted. Goodnow*342	—Let safety help the war
Penn. Fuel Co. license restored. (Note)1095 Pennwell Coal Co.—Coal mined 1918.	Props, Reinforced concrete pit. Meredith. 362 Protect equipment from lightning 459 Provincial rights dispute in Canada. Dunn. •352	-Mine safety in wartime. Harrington 638
(Note)	Provincial rights dispute in Canada. Dunn. *352	-Odor warning. Tests on
Perplexities of mine foremen. Discussion.	Pryde, G. B. Wartime economies	—Powder flasks and fire pails
Perry Coal & Sand Co	Pulley. (Photo)	—Progress in accident prevention 483 —Rescue, mine, work. Discussion 32, 283, 656
Perry Coal & Sand Co. 1047, 1176 Persons, C. E. director of education. 699 Phelps Dodge Corp.—Y. M. C. A. Willis. *486	Pulverized fuel 184	-Safeguards in anthracite breakers and
rumppine coal fields develop slowly 384	PUMPING	washeries. Glover 901 —Safety relies on "come-along" spirit 517
Pillar workings. Discussion	—Centrifugal mine pumps. (inq.)1049	-Sealing off fire on intake. Discussion.
Pipe Device for bending small. Jaross*251 Pipe fitting simplifies shaft leveling.	—Handling mine water. Cole	*33, 143, *187, 236, 285, 520 —Shotfiring in mines. Discussion 234, 327
(Photo)	-Pump repair. Hainley*1105	-Squibs vs. electric fuse. (inq.) 145, Dis-
Pipe, Hickey for bending	-Triplex pump, wood lined	cussion328, 519
Pioneer anthracite mining engineer*825 Pittsburgh Terminal R.R. & Coal Co.—	-Water indicator and motor stop. Husk-	St. Louis Rocky Mtn. & Pacific CoSugar-
Meeting 272 Planning, town. Miller. *130 Plant, J. H. Wire-poe formulas. 1137 Playgraphy (Perope formulas. 225	inson*358 Purchase of mining machinery and supplies.	ite. N. Mex. plant. Huskinson 14
Plant, J. H. Wire-rope formulas137	Bowron 782	Sakon, F. W. Resistance terminal connec- tions. *581
Playground, (Photo)		tions
Playground. (Photos). 325 Pocock, F. A. Coal mining and man power 350 Poetry *155, *201, *354, *385, *427, *540, *625, *807, 1015	R	Saving coal
*625, *807, 1015		Saw Portable for mine use
Portal, Unique mine. Mayer*909 Porter, H. K. Maximum production for	Rail. Elevation of outer. Discussion 284	Scattering what we have garnered 996 Schaack D V. (Photo) 485
humanity's sake *97. Hauling capacity of	Rails, Cause of brittleness in mine, Crevel-	Schaphorst, W. F. How big is 150,000,000
locomotives	ing (inq.)	Scheble M C Raising two 350-hp boilers. 392
Posters 29, 74, 139, 281, 370, 412, 460, 515, 563, 610, 653, 706, 749, 792, 832, 868, 872, 912, 955, 998, 1043, 1084,	Rails, Straightening bent. Butler 722	Scholz, C. Auxiliary power to drive fan. 76 Schwartz, E. Grease cup filler *930, Removing broken studs
868, 872, 912, 955, 998, 1043, 1084,	Kalls, Straightening brittle, Discussion 77	Schwartz, E. Grease cup filler *930, Re-
Posters to boost coal tonnage	Railroad accidents	Scranton Coal Co., fire. (Note)1094
Powder flasks	Railroad congestion	Scraper mining in low seams 371
Powell, J. W. Sealing off fire on intake 285, Squibs vs. electric fuse, 519, Ven-	Railroads—Gov't. ownership1086	Scraper mining of thin bed anthracite. Humphrey*316
tilating a gassy slope mine *566. Working 10-ft. inclined seam *611. Simple derail-	Railroads make raid on production 231 Railroads moving more coal this year 786	Humphrey
10-ft. inclined seam *611. Simple derailing device *931, Iron vs wood mine cars999	Pailroade should deliver clean care 1179	Screenings, Must find market
Power of coals and gas. Owens 312	Railway, Virginian, coal pier	Screwdriver, crank
POWER See also "Roiler" "Freine" etc	Railway, Virginian, coal pier 1122 Rainey, W. J. Interests, Byproduct coke. 256 Rainey, Wood Coke Co 20 Ramsey, G. W. Mine-car door *140, Wind-	
POWER. See also "Boiler," "Engine," etc.  —Automatic circuit breakers	ing armatures	Security Coal & Mining Co. plant263
-Auxiliary power to drive fan. Discussion *76 -Coal saving at power plants 905	Raymond M Increased production with	Seeing the boss wastes time and temper 791 Senate investigating coal industry 994.
—Demand and consumption as to canacity	modern machinery *127, New type of screen *589	1038, 1125
and production	Read, R. G. Simpson Creek Coal Co.'s tip-	Serviss, F. L. Surveying and mapping 30,
-Fuel Administration to settle power con-	ples	Value of the mining engineer 708, Coal—how analyzed
troversy	Reconstruction, Days of. Parsons 721	Sewer pipe for water lines
—Increasing coal mine efficiency. Stuart *724, 773, *830, *857, *903	Reconstruction, Days of. Parsons	Shaft, Freezing of, in winter. Discussion.
-Isolated to central station power. Husk- inson. •14	Records Careful reduce mine accidents	*1134, 1175 Shaft pillars in mines, Size of 230
-Isolated plant vs. purchased power1173	Fay 503 Rocovery plant, Effective 10 Red Cross. (Photos) 403, (Poster) 1084,	Shaft problems Hoisting. (inq.)1049
-Luzerne County Electric Co. combination. (Note)	Reëstablishment or reconstruction 954	Shaft relined with cement gun
	Rehabilitation work. (Notes)	Shells. Coal mining and three-inch 459
Hines. *50 —Motor generator set. (Photo). 892	Reminiscences of a life-long friend. Rice 875 Repairs. Now is time for. Seaburg 2	Sheridan Coal Co. (Photo)
—Power house at Cassidy's. (Photo) 981 —Steam power plant conservation 319	Report sheet	Chipments coal (Notes) 140 170 401
—Steam turbine units, Terry. (Photo) 64	Rescue mine work Discussion 32 283.	Shipments, Lake. (Notes) 275, 923, 1169, 1188 Shipments, Lake. (Notes) 275, 923, 1169, 1188 Shipments, zoning system. Discussion1132
-Substations, anthracite distribution sys-	656, 1001  Rescue. (Notes)	Shipments, zoning system. Discussion1132 Shipping facilities at the world's largest
tem. *850  —Substations, Outdoor mine. Young. *891  —Substation, underground synchronous. *434	Rescue—Paul breathing apparatus 864	Shipping facilities at the world's largest
Hines*434	Rescue work at fairs 320 Rescue work, Material needed 930	coal mine. Mayer
Hines		Shotfiring. See "Blasting."
PREPARATION		
—Breaker, all-steel. (Note)	Responsibility. Braley	Shovel, Erie
The steel (Note)	Research. Engineering 852 Responsibility. Braley 354 Resuscitated after long treatment 497 Retail coal and coke dealers to register	Shovels, electric, Loading out coal, Bren-
-Equipment used in Pacific northwest *18 -Jigs. Elmore. *18		Shovels, electric, Loading out coal. Brennan*1018 Shovels, electric, Underground mining, Witt-
Equipment used in Pacific northwest *18 Jigs. Elmore *122 Plant of Williams Pocahontas Coal Co.		Shovels, electric, Loading out coal. Brennan
Equipment used in Pacific northwest *18 Jigs. Elmore. *122 Plant of Williams Pocahontas Coal Co. Jaxon. *1106	Ketali coal and coke dealers to register. (Note) 1053 Revenue bill, Changes in 603 Reward for patriotism in West Va 740 Revnolds E. D. Locating the coal beyond	Shovels, electric, Loading out coal. Brennan
Equipment used in Pacific northwest. •18 Jigs. Elmore. •122 Plant of Williams Pocahontas Coal Co Jaxon. •1106 Screen, Marcus, at Carnegie Coal Co.	Note	Shovels, electric, Loading out coal. Bren- nan
Equipment used in Pacific northwest . *18 Jigs, Elmore	Note	Shovels, electric, Loading out coal. Bren- nan
Equipment used in Pacific northwest. •18 Jigs. Elmore. •122 Plant of Williams Pocahontas Coal Co Jaxon. •1106 Screen, Marcus, at Carnegie Coal Co.	(Note) 1053 Revenue bill, Changes in 603 Reward for patriotism in West Va. 740 Reynolds, E. D. Locating the coal beyond a fault 1088 Reynolds S. C. Snow-Bird mine 158 Reynolds Viscount, Death of 64 Rice, C. T. Device for binding timbers on a truck 488	Shovels, electric, Loading out coal. Bren- nan
Equipment used in Pacific northwest. *18 Jigs, Elmore	(Note)	Shovels, electric, Loading out coal. Brennan 1018 Shovels, electric, Underground mining, Witthoff 1016 Signaling 936 Signaling in British coal mines, Walker 980 Signal system on mine slope, Brehm 479 Signal to indicate discontinuance of load 723 Simpson Creek Coal Co.'s tipples 430 Sines, cosines, etc. (inq.) 465 Single purpose, Parsons 249
Equipment used in Pacific northwest. *18 Jigs, Elmore. *122 Plant of Williams Pocahontas Coal Co. Jaxon. *1106 Screen. Marcus. at Carnegie Coal Co. Miller. *171 Screen. New type. Raymond. *589 Surface plant of Orient mine. *932 Tipple at Parnassus, Penn. Jaxon. *582 Preservative treatment of mine timbers. Barth. *1025 Price T. F. Firing wet holes 48 Finding.	(Note)	Shovels, electric, Loading out coal.  Browles, electric, Underground mining, Witthoff . 1018  Signaling . 936  Signaling in British coal mines, Walker . 986  Signal system on mine slope, Brehm . 479  Signal to indicate discontinuance of load . 723  Simpson Creek Coal Co.'s tipples . 430  Sines, cosines, etc. (inq.) . 465  Single purpose, Parsons . 249  Situation, Mining, Discussion . 78, 144, 186  Sizes of fresh-mined anthracite . 780
Equipment used in Pacific northwest. *18 Jigs, Elmore. *122 Plant of Williams Pocahontas Coal Co. Jaxon. *1106 Screen, Marcus, at Carnegie Coal Co. Miller. *171 Screen, New type, Raymond. *589 Surface plant of Orient mine. *932 Tipple at Parnassus, Penn. Jaxon. *582 Preservative treatment of mine timbers. Barth. *1025 Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal. Brennan *1018 Shovels, electric, Underground mining, Witthoff *1016 Signaling 936 Signaling in British coal mines Walker 986 Signal system on mine slope. Brehm *479 Signal to indicate discontinuance of load *723 Simpson Creek Coal Co.'s tipples 430 Sines, cosines, etc. (inq.) 465 Single purpose. Parsons 249 Situation, Mining Discussion 78, 144, 186 Sizes of fresh-mined anthracite 780 Skip-stop coal saving 866 Skip-stop coal saving 868 Skip-stop coal saving 111
Equipment used in Pacific northwest. *18 Jiss. Elmore. *122 Plant of Williams Pocahontas Coal Co. Jaxon. *1106 Screen. Marcus. at Carnegie Coal Co. Miller. *171 Screen. New type. Raymond. *589 Surface plant of Orient mine. *932 Tipple at Parnassus. Penn. Jaxon. *582 Preservative treatment of mine timbers. Barth. 1025 Price. T. F. Firing wet holes 48, Finding the dump pivot *202. Automatic tipple switch. *250	Retail coal and coke dealers to register.  (Note) 10.53 Revenue bill, Changes in 603 Reward for patriotism in West Va. 740 Reynolds E. D. Locating the coal beyond a fault 10.88 Reynolds S. C. Snow-Bird mine 10.88 Reynolds S. C. Snow-Bird mine 10.88 Reynolds S. C. Snow-Bird mine 10.88 Reynolds Viscount, Death of 16.64 Rice C. T. Device for binding timbers 16.64 Rice G. S. Rominiscences of a life-long 16.64 Rice G. S. Rominiscences of a life-long 16.64 Rice A. F. report. (Note) 10.95 Richardson, G. A. Steel mine ties 11.2 Roan, J. M. Charge of clean coal inspectors 12.1	Shovels, electric, Loading out coal. Brennan
- Equipment used in Pacific northwest. *18 - Jigs. Elmore. *122 - Plant of Williams Pocahontas Coal Co.     Jaxon. *1106 - Screen. Marcus. at Carnegie Coal Co.     Miller. *171 - Screen. New type. Raymond. *589 - Surface plant of Orient mine. *932 - Tipple at Parnassus. Penn. Jaxon. *582 Preservative treatment of mine timbers.     Barth. 1025 Price. T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch. *250 Prices, bituminous coal fixed. Garnsey.     Norris and Allport. *685, 736	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal. Brennan 1018 Shovels, electric, Underground mining, Witthoff 1016 Signaling 936 Signaling in British coal mines, Walker 986 Signal system on mine slope. Brehm 479 Signal to indicate discontinuance of load 473 Simpson Creek Coal Co.'s tipples 430 Sines, cosines, etc. (inq.) 465 Single purpose, Parsons 249 Situation, Mining, Discussion 78, 144, 186 Sizes of fresh-mined anthracite 780 Skip-stop coal saving 866 Slight mixing of words 111 Sloman M. S. Cement gun in bituminous coal mine 1158 Slush line joints 428
- Equipment used in Pacific northwest. *18 - Jigs. Elmore. *122 - Plant of Williams Pocahontas Coal Co.     Jaxon. *1106 - Screen. Marcus. at Carnegie Coal Co.     Miller. *171 - Screen. New type. Raymond. *589 - Surface plant of Orient mine. *932 - Tipple at Parnassus. Penn. Jaxon. *582 Preservative treatment of mine timbers.     Barth. 1025 Price. T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch. *250 Prices, bituminous coal fixed. Garnsey.     Norris and Allport. *685, 736	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining. Witthoff of the signaling of the signaling of the signal of the s
Equipment used in Pacific northwest. *18 Jiss, Elmore. *122 Plant of Williams Pocahontas Coal Co Jaxon. *1106 Screen, Marcus, at Carnegie Coal Co Miller. *171 Screen, New type, Raymond. *589 Surface plant of Orient mine. *932 Tipple at Parnassus, Penn, Jaxon. *582 Preservative treatment of mine timbers Barth. 1025 Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch *250 Prices, bituminous coal fixed. Garnsey, Norris and Allport 685, 736 Prices, Brazil 160 Prices, coal. 22, 67, 195, 226, 275, 378, 406, 744, 950, 1039, 1168	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining. Witthoff  Signaling:  Signaling:  Signaling:  Signal system on mine slope. Brehm.  479  Signal to indicate discontinuance of load.  Simpson Creek Coal Co.'s tipples.  430  Sines, cosines, etc. (inq.)  Single purpose. Parsons.  Situation, Mining. Discussion.  78, 144, 186  Sizes of fresh-mined anthracite.  780  Skip-stop coal saving.  866  Slight mixing of words.  111  Sloman M. S. Cement gun in bituminous coal mine.  *1158  Slush line joints.  428  Smillie S. Cost of upkeep of mine cars.  1174  Srapshots in coal mining.  851
	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining, Witthoff . 1016 Signaling . 936 Signaling in British coal mines Walker . 986 Signal system on mine slope. Brehm . 479 Signal to indicate discontinuance of load . 723 Simpson Creek Coal Co.'s tipples . 430 Sines, cosines, etc. (inq.) . 465 Single purpose. Parsons 249 Situation, Mining, Discussion 78, 144, 186 Sizes of fresh-mined anthracite . 786 Skip-stop coal saving . 866 Slight mixing of words
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co.  Jaxon. *100  — Screen. Marcus. at Carnegie Coal Co.  Miller. *171  — Screen. New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus. Penn. Jaxon. *582  Preservative treatment of mine timbers.  Barth. 1025  Price. T. F. Firing wet holes 48. Finding the dump pivot *202. Automatic tipple switch  Prices, bituminous coal fixed. Garnsey.  Norris and Allport . 685. 736  Prices, Coal. 22, 67, 195, 226, 275, 378.  406, 744, 950, 1039, 1168  Prices, Coal. in Ireland. 936  Prices, Coal. in Ireland. 936  Prices, Current, materials and supplies 45, 247, 475, 671, 1101	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal. Brennan
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co. Jaxon. *1106  — Screen, Marcus, at Carnegie Coal Co. Miller. *171  — Screen, New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus, Penn. Jaxon. *582  Preservative treatment of mine timbers. Barth. 1025  Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch. *250  Prices, bituminous coal fixed. Garnsey. Norris and Allport 685, 736  Prices, Coal. 22, 67, 195, 226, 275, 378, Prices, Coal, in Ireland. 936  Prices, Current, materials and supplies 45, Prices, Current, materials and supplies 45, 247, 475, 671, 1101  Prices, German pre-war and present coal. 642	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining, Witthoff Signaling.  Signaling in British coal mines, Walker.  Signal system on mine slope. Brehm.  479 Signal to indicate discontinuance of load.  Simpson Creek Coal Co.'s tipples.  430 Sines, cosines, etc. (inq.)  Single purpose. Parsons.  249 Situation, Mining. Discussion.  78, 144, 186 Sizes of fresh-mined anthracite.  780 Skip-stop coal saving.  866 Slight mixing of words.  Sloman M. S. Cement gun in bituminous coal mine.  2118 Sush line joints.  428 Smillie S. Cost of upkeep of mine cars.  1174 Srapshots in coal mining.  428 Snow-Bird mine. Reynolds.  58 Socketing wire ropes.  343 Somers, J. Specializing in the mine.  108 Southern Mg. Co. (Photo) Southern Mg. Co. (Photo) Snaht. A. W. Trayel of electric current.
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co.  Jaxon. *1106  — Screen, Marcus, at Carnegie Coal Co.  Miller. *171  — Screen, New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus, Penn. Jaxon. *582  Preservative treatment of mine timbers.  Barth. 1025  Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch. *250  Prices, bituminous coal fixed. Garnsey.  Norris and Allport	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining, Witthoff . 1016 Signaling . 936 Signaling in British coal mines Walker . 986 Signal system on mine slope. Brehm . 479 Signal to indicate discontinuance of load . 723 Simpson Creek Coal Co.'s tipples . 430 Sines, cosines, etc. (inq.) . 465 Single purpose. Parsons 249 Situation, Mining. Discussion 78, 144, 186 Sizes of fresh-mined anthracite . 786 Skip-stop coal saving . 866 Slight mixing of words . 111 Sloman M. S. Cement gun in bituminous coal mine 1158 Smillie S. Cost of upkeep of mine cars 1174 Smillie S. Cost of upkeep of mine cars 1174 Snow-Bird mine Reynolds . 58 Socketing wire ropes 488 Socketing wire ropes
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co.  Jaxon. *1106  — Screen. Marcus. at Carnegie Coal Co.  Miller. *171  — Screen. New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus, Penn. Jaxon. *582  Preservative treatment of mine timbers.  Barth. 1025  Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch *250  Prices, bituminous coal fixed. Garnsey.  Norris and Allport .685, 736  Prices, Coal. 22, 67, 195, 226, 275, 378, 406, 744, 950, 1039, 1168  Prices, Coal. in Ireland. 936  Prices, Corrent, materials and supplies 45, 247, 475, 671, 1101  Prices, German pre-war and present coal .642  Prices materials and supplies 45, 247, 475, 671, 1101  Prices materials and supplies 45, 247, 475, 671, 187  Prices. New schedule of anthractes.	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal. Brennan 1018 Shovels, electric, Underground mining, Witthoff 1016 Signaling 936 Signaling in British coal mines Walker 986 Signaling in British coal mines Walker 986 Signal system on mine slope. Brehm 479 Signal to indicate discontinuance of load 723 Simpson Creek Coal Co.'s tipples 430 Sines, cosines, etc. (inq.) 465 Single purpose. Parsons 249 Situation, Mining Discussion 78, 144, 186 Sizes of fresh-mined anthracite 780 Skip-stop coal saving 866 Skip-stop coal saving 866 Skip-stop coal saving 811 Sloman M. S. Cement gun in bituminous coal mine *1158 Sush line joints 428 Smillle S. Cost of upkeep of mine cars 1174 Snow-Bird mine. Reynolds 538 Socketing wire ropes 343 Somers, J. Specializing in the mine 109 Spanish influenza Parsons 767; (Posters) 792 S72; (Notes) 714, 758, 799, 839, 867 Specializing in the mine Appleton and
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co.  Jaxon. *1106  — Screen. Marcus. at Carnegie Coal Co.  Miller. *171  — Screen. New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus, Penn. Jaxon. *582  Preservative treatment of mine timbers.  Barth. 1025  Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch *250  Prices, bituminous coal fixed. Garnsey.  Norris and Allport .685, 736  Prices, Coal. 22, 67, 195, 226, 275, 378, 406, 744, 950, 1039, 1168  Prices, Coal. in Ireland. 936  Prices, Corrent, materials and supplies 45, 247, 475, 671, 1101  Prices, German pre-war and present coal .642  Prices materials and supplies 45, 247, 475, 671, 1101  Prices materials and supplies 45, 247, 475, 671, 187  Prices. New schedule of anthractes.	Retail coal and coke dealers to register.  (Note) 11. Changes in 603 Rewernde bill, Changes in 603 Reward for patriotism in West Va. 740 Reynolds, E. D. Locating the coal beyond a fault 1088 Reynolds S. C. Snow-Bird mine 558 Rhondda, Viscount, Death of 664 Rice, C. T. Device for binding timbers on a truck 668 Rice, G. S. Rominiscences of a life-long friend 1095 Richardson, G. A. Steel mine ties 112 Roan, J. M. Charge of clean coal inspectors 12 Rocky Mountain Coal Mg. Inst.—Meeting and papers 633 Roddie, J. M. First aid to the uninjured 283 Roof support 1159 Rope formulas Wire (inq.) Plant 1137 Ropes, wire, socketing 117 Ropes, wire, socketing 343 Rose, J. Perplexities of mine foremen 1002	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining. Witthoff
— Equipment used in Pacific northwest. *18 — Jigs. Elmore. *122 — Plant of Williams Pocahontas Coal Co. Jaxon. *100 — Screen. Marcus. at Carnegie Coal Co. Miller. *171 — Screen. New type. Raymond. *589 — Surface plant of Orient mine. *932 — Tipple at Parnassus, Penn. Jaxon. *582 Preservative treatment of mine timbers. Barth	Retail coal and coke dealers to register.  (Note) 11. Changes in 603 Rewernde bill, Changes in 603 Reward for patriotism in West Va. 740 Reynolds, E. D. Locating the coal beyond a fault 1088 Reynolds S. C. Snow-Bird mine 558 Rhondda, Viscount, Death of 664 Rice, C. T. Device for binding timbers on a truck 668 Rice, G. S. Rominiscences of a life-long friend 1095 Richardson, G. A. Steel mine ties 112 Roan, J. M. Charge of clean coal inspectors 12 Rocky Mountain Coal Mg. Inst.—Meeting and papers 633 Roddie, J. M. First aid to the uninjured 283 Roof support 1159 Rope formulas Wire (inq.) Plant 1137 Ropes, wire, socketing 117 Ropes, wire, socketing 343 Rose, J. Perplexities of mine foremen 1002	Shovels, electric, Loading out coal. Brennan *1018 Shovels, electric, Underground mining. Witthoff *1016 Signaling 936 Signaling in British coal mines. Walker 986 Signal system on mine slope. Brehm *479 Signal to indicate discontinuance of load *723 Simpson Creek Coal Co.'s tipples 430 Sines, cosines, etc. (inq.) 465 Single purpose. Parsons 249 Situation, Mining. Discussion 78, 144, 186 Sizes of fresh-mined anthracite 488 Skip-stop coal saving 868 Skip-stop coal saving 868 Skip-stop coal saving 8111 Sloman M. S. Cement gun in bituminous coal mine. *1158 Sush line joints 428 Smillle S. Cost of upkeep of mine cars 1174 Snow-Bird mine. Reynolds 588 Socketing wire ropes 343 Somers, J. Specializing in the mine 109 Southern Mg. Co. (Photo) 307 Spaht, A. W. Travel of electric current 189 Spanish influenza. Parsons. 767: (Posters) 792. 872: (Notes) 714, 758, 799, 839, 867 Specializing in the mine. Appleton and Somers 6109 Specific gravity of coal. Blakeley 1078, Erratum 1165
— Equipment used in Pacific northwest. *18  — Jigs. Elmore. *122  — Plant of Williams Pocahontas Coal Co.  Jaxon. *1106  — Screen. Marcus. at Carnegie Coal Co.  Miller. *171  — Screen. New type. Raymond. *589  — Surface plant of Orient mine. *932  — Tipple at Parnassus, Penn. Jaxon. *582  Preservative treatment of mine timbers.  Barth. 1025  Price, T. F. Firing wet holes 48, Finding the dump pivot *202, Automatic tipple switch *250  Prices, bituminous coal fixed. Garnsey.  Norris and Allport .685, 736  Prices, Coal. 22, 67, 195, 226, 275, 378, 406, 744, 950, 1039, 1168  Prices, Coal. in Ireland. 936  Prices, Corrent, materials and supplies 45, 247, 475, 671, 1101  Prices, German pre-war and present coal .642  Prices materials and supplies 45, 247, 475, 671, 1101  Prices materials and supplies 45, 247, 475, 671, 187  Prices. New schedule of anthractes.	Retail coal and coke dealers to register. (Note)	Shovels, electric, Loading out coal.  Shovels, electric, Underground mining. Witthoff

Page	Page	Page
Spending and helping the enemy 49	TIMBERING—Continued —Preservative treatment of mine timbers.	VENTILATION—Continued —Fans and boilers. Owens
Sperr, F. W. Byproduct coking practice. 1068, *1114, *1156	Barth	—Gassy slope in mine, Ventilating. (inq.)
Springer, J. F. Concrete foundations *204, *628 Squeals, All but the	—Terms used in timbering	191 Discussion 326, 372, 564, 914  —Natural mine ventilation. (inq.) 330
Stafford M. Mine-car door *141. Sealing	Tipple. Madison Coal Corp	-Origin and development of ventilating fan
off fire on intake *188, Alarm bell on mine car *429, Suggestion for a sharp	Tipple, Peabody Coal Co	—Power consumption and demand of mine
curve •722, Method of working thick	Tithing America for world's benefit1172	fans
Standard Oil Co1140	Tipton, J. H. Hindrances to coal produc- tion	—Reducing ventilation at firing time. Dis-
Statistics, Standardization of mine 27 Steam, Raising, with waste products of	tion	cussion
vesterday	Schaphorst	—Shaft for water hoisting and ventilation. *397 Verner, J. Reducing ventilation at firing
Steck, E. Estimating power in haulage 833 Steel for chutes, Rejected shell 649	Tools up a ladder, Dangerous to carry*273 Tool rack, Clothespins useful as. (Photo) 674	time
Steel switching cabinet*742 Steel tires vs. chilled iron wheels. Discus-	Tool tray, non-tipping	Vicary, A. C. Increased output by strip-
sion	Tracks—Coal mine efficiency. Stuart 820 Track, Elevation of outer rail. Discussion. 284	ping *94 Victor-American Fuel Co. (Photo) 65 Virgin, R. Z. Education, financial and so-
Steels, cross-sections of iron and. (Photo). 220 Stefansson discovers coal in north. (Note). 618	Track, Elevation of outer rail. Discussion. 284 Track—Steel mine ties. Richardson*112	cial barometer 446
Stick to your job. Strohm	Track—Steel lillie ties. Mchardson 115	Virginia prices
ditions 393. Development period of a	TRADE	Vise. Carrying a heavy
mine	—Buyers, Patriotic duty of. Hall 929 —Cargo and coal handling methods at	Voice from the trenches. Strohm *201. Discussion
Stonega Coal & Coke CoMiners' Safety.	American ports	,
Mandel	-Exports 213, 335, 604, 827, 866, 907, 1039, 1169	w
Storage, bituminous, increase authorized 785	Freight rates. (Notes)	"
Storage, bituminous, limit off	—Holland to get American coal827, 865	Wages. See "Labor."
Storage policy of Fuel Administration 405 Storage regulations, Revision 602	—Imports	Wagon mine a menace. Discussion. 282, 464, 834
Storage, Some new ideas in coal 174	—Lake coal handling charges 364	Wagon mines in Pittsburgh, Better prices 274
Storage suggestions. Stock	-Markets, to keep Germany from our 911 -Order closing Lake trade 950	Walker, S. F. Signaling in British coal
Stored at the mines, If coal had been	-Retail prices hard and soft coal 827 -Retailers must file reports 68	
miner?	-Shipments, anthracite increase 601	Warrior River Barge. (Notes)147, 713,
miner? 539 Straight stuff. Braley 625 Stripping (Notes) 37 378	—Shipments, Lake275, 923, 1169, 1188 —Tithing America1170	WAR TOPICS 799, 1168
Stripping. (Notes)	—Venice, Coal trade,	—After the war
Strinning coal with a grader 694	Traer, G. W. Low temperature distillation	—Back to the mines. Strohm1103
Stripping, Increased output by. Vicary *94 Stripping, Worland, Mo. (Photo) 449 Strohm, R. T. The interpretation *155,	of Ill. and Ind. coals	—British coal supplies
A voice from the trenches *201, The	Transportation of coal by canal. Discus-	—Coal industry's part in war. Cornwell 695
lucky thirteen *385, The heroes of the	rautschold, R. Coal production and lubri-	—Coal mining is war work
pick *427, Think man think *477, Stick to your job 741, The invincibles 1015,	cation	Stock
Back to the mines	Travel of electric current. (inq.) 35, Discussion	
Stuart, C. E. Increasing coal mine efficiency *724, *773, *820, *857, *903,	Traveling toward daylight. Parsons 47 Trego, F. H. Mine safety appliances in	District representatives133, 149, 994  —Do your bit
Sketch	warfare	-Don't let up till he puts up both hands.
Substations, Outdoor mine. Young*891	Trevorton Coal Co.—Hoisting at Catherine colliery*165	
Sulphur, Reclaiming	Trolley construction for mines	—Don't call miner till you want him 508 —Drafting miners. (Notes)180, 182, 239 289, 290, 467, 557, 839
Surveying and mapping, Discussion, 30	Truck, motor. (Photo) 58	
Surveying—Cold weather instrument work. 790 Surveying—Latitude and meridian. Callen. •168	Truck, Removable, switchboard units*1166 "Tuckahoe" breaks previous records 452	—Economies, Wartime. Pryde 633 —Enemy alien return? Will. 830
Susquehanna River navigable. (Note)1057	100000 10000 100000 11111 400	Engineers' regiment rejects miners 408
Sutherland, G. W. Oblique faced rooms 580	U	-Enlistment of Shorty McGee. Fletcher*807 -Exemption of W. Va. miners229, 709
Switch, automatic Ramsay	UNITED KINGDOM	-Filling the Liberty Loan quota 750 -Flag at your tipple. (Poster) 653
Switch, automatic tipple. Price	—British mine accidents1164	-Flag Our international 1130
Switch. Calculating a room. (inq.) 756, Discussion	Byproduct coking in Great Britain, Ker-	—Forging the blade. (Cartoon)
Switch—Frogs and latches. (inq.)1179 Switch, mine, calculations. (inq.)961	shaw	Canadian
owner, mine, carculations. (inq.)	—Great Britain's fuel research. Meredith. 642 —Macclesfield gas works. Meredith 129	Canadian
m ·	Macelesfield gas works. Meredith 129 North of Eng. Inst. of Mg. & Mech Engrs. (Paper)	—Furlough from military service
•	-Prices, Coal, Ireland. 936	—Here's where your coal is at fighting
Table—Bituminous coal consumption, U.S.	—Recovery plant, Effective	front. (Poster)
1915	-South Wales coals	Hun propaganda. Parsons 673  —Interpretation. The. Strohm 155  —Keep it burning. (Cartoon) 651  —Let safety help the war 847  —Let us be liberal hosts to our men. 870
Table—Entry progress. Hampsch 63	-Winning the war with coal. Fisher 986	Keep it burning. (Cartoon)
Tables—Coke	United Mine Workers' election1040	—Let safety help the war
parture notes. Hampsch*768	UNITED STATES	
Tague, J. Americanizing the foreigner 708 Taxation, Fair and unfair	-Coal to Holland. (Note)	toon)
Taxation, mine		sion
tering 13. Credit of the coal man 267	Peat deposits	-Make your dollars protect her. (Car-
Taylor, J. H. Loading coal at the face 567 Teamwork between engineer and mine fore-		toon) 634  —Men or coal? (Cartoon) 638  —Mine foreman a general in fray 509  —No covenanted peace with Germany 655  Ordroved ordrodes a company 655
man	U. S. Coal & Coke Co.—Patriotic work at	-No covenanted peace with Germany 655
Telephone, electric mine	Gary	—Ordnance dept. officials transferred 603
Telephone, switchboard, mine. (Photo) 895 Tendency of the times	Utah Fuel Co.—Unusual bounce condition. Watts	—Ordnance dept. officials transferred 603 —Partners with the Kaiser. Kneeland 579 —Patriotism with booze. You can't com-
Terminology of coal deposits. 72 Testing for gas in mines. Gray. 217 Testing—Methane as a fuel. Williams. 988	77000	bine. (Poster)
Testing—Methane as a fuel. Williams*988	v	Peace without victory
Testing—Specific gravity of coal. Blakeley. 1078. Erratum	Valley Comp Coal Co's timple at Parmas	
Them were the happy days	Valley Camp Coal Co.'s tipple at Parnassus. Penn. Jaxon	—Problem in division. (Poster)
They are not hoisting booze but coal.	Value of the mining engineer. Discussion. 708 Value grinding. (Photo)	
(Cartoon)	Valve grinding. (Photo) 675 Valve seat remover. (Photo) 674 Vancouver coal utilized by U. S. Navy.	Responsibility. Braley*354  Safety. Mine, Appliances in warfare.
This is the day of the spoken word 562 Thomas, J. R. Ventilating gassy slope in	(Note)	—Saving materials—a way to victory
mine 326. The miner and his pleasure	Vancouver Island production20, 210 Vein, seam, horizon, blanket or bed?	Trego
463, Hindrances to coal production 710, Blackdamp on pitches 753, Justice to the	Vein, seam, horizon, blanket or bed? 72 Venezuela coal mines	
miner 916 Estimating percentage of	Venice, Coal trade1153	—Solective service not to blame. 278 —Shall we traffic with Germany? 910
grade 959, Miner and safety	VENTILATION. See also "Gases, Mine,"	
mining 518, The miner and safety 877.  Justice to the miner1047	Booster fans. Use and location. Discussion	Single purpose. Parsons 249  Slacker boards in West Virginia 433  Slackers in mines, Discussion 413, 461  Smokeless coal, Advantage of burning 509  Restors 740
Thompson, C. H. Portable coal loaders1135	cussion 461 659  —Calculating velocities of air (inq.) 417 —Emergency ventilator Jennson 627 —Elements in mine ventilation (inq.) 1137 —Elements in mine ventilation (inq.) 127	—Slackers in mines. Discussion413, 461 —Smokeless coal. Advantage of burning 509
Ties, Steel mine. Richardson*112	-Elements in mine ventilation. (inq.)1137	
TIMBERING	Fan Auxiliary power to drive Discus-	Spending and helping the enemy 49 Stamps, War savings 29 Stokers lose heart. (Poster) 610 Straight stuff. Braley 625
—Dog for lowering mine timbers*386 —Pulling heavy timbers. Lawton*626	sion	—Stokers lose heart. (Poster)
		were state of the

Page	Page	Pag
WAR TOPICS—Continued —Traveling toward daylight. Parsons 47	Who gets hurt and when?	WORKING MINES—Continued —Longwall, Advantages. Pocock
-Untrained men will not serve our ends 609	*818, *861, *897, *1037, *1075	-Longwall mining at La Salle, Ill. Har-
Volunteer coalers	Wholesale Coal Trade Assn.—Coal exchange	ris*38 —Longwall mining, Man power and dis-
-War is won now let us win peace 889	Why we pay more for cleaned coal 654	cussion*564. 79 —Machine mining at La Salle, Ill. Harris*53
—We've started something	Wilkins, G. W. Transportation of coal by canal	-Methods of operation. Brown 31
Washington, Coal mining in Carbonado, Jar-	Williams, B. W. Use of methane as a fuel. 988	—Oblique faced rooms. Sutherland*58 —Pitch. Working a 22-deg. (inq.) 83
Waste due to excessive ash in coal*692	Williams Pocahontas Coal Co. Jaxon*1106 Williams, S. J. (Photo)	-Pitching beds worked by longwall. Jar-
Waste gases for steam generation. Ker-	Willis, C. F. Y. M. C. A. building vs. "Y" hut	rett*30
shaw	Winn, W. E. Hinckston Run mine 647	—Scraper mining of thin bed anthracite.  Humphrey
Water indicator and motor stop. Huskin- son*358	Wire coil made on screw. (Photo)	—Scraper mining in low seams. Discussion
Water-power development 655	Wisconsin Steel Co. (Photo) *702, Fire1140	—Shortwall mining machine. (Photo) 32
Waterproofing cement work. (inq.)1092 Watkins, T. H. Letter to mine foreman 560	Witthoff, E. J. Underground mining with electric shovels	—Standardized system of mining*266 —Stripping, Anthracite. Kennedy*644
Watson, C. W. Sketch, (Portrait) 818	Wood, Iowa, (Note) 965	—Stripping coal with a grader
Watson, M. M. The mining situation 235 Watts, A. C. Unusual bounce condition*1028	Wood, R. J. Shortage of mine labor 79 Wooton, P. News from the capital, 21, 67,	-Thick coal. Method of working. Staf-
Weir, J. Mine-rescue work1001	133, 178, 225, 274, 319, 363, 405, 451, 513, 556, 602, 648, 698, 744, 785, 826,	ford*890 —Underground mining with electric shov-
Weitzel E. H. Justice to the miner 753 We must all grow old some time. (Poster), 515	865, 905, 949, 992, 1038 1125, 1168	els. Witthoff*1016
Western Fuel Co.—Harewood mine 59. Broken cable	Work will win the war 272	Working 10-ft. inclined seam*611 Wrench, Ratchet. Lucas*1104
West Kentucky Coal Co.—Fire. (Note) 290	WORKING MINES. See also "Cutter. Coal."	Wienen, Matchet. Edcas
West Va., Neglected coal field 595 We've started something 704	"Hoisting." Haulage," "Electricity." "Power." "Pumping," "Timbering."	Y
What is the matter with the miner?	—Block system	York, G. D. Elevation of outer rail of
Stow	—Bounce condition, unusual. Watts *1028 —Brantley coal cutter *596	York. G. D. Elevation of outer rail of track Y. M. C. A, building vs. "Y" hut. Willis 486
Wheeler, D. I. Mine motor*1167 Wheels. Steel tires vs. chilled-iron. Dis-	—Conveyor, Reciprocating underground.  Brown	Young. H. W. Outdoor mine substations *891
cussion	-Conveyor, Simple face. Davis *92, Dis-	Your troubles. Parsons 341
When John no longer defers to you 705 When your neighbor is angry 654	cussion	Z
White Coal Co., E. E Boosting produc-	—Cutters, Coal	Pil
tion	—Deeper mining in years to come	Ziegler mine. Harris
White, J. L. Sealing off fire on intake 373 White Sulphur Springs meeting 605	-Locating coal beyond fault. (inq.). *797. Discussion	Zoning system of coal shipments. Discussion
water author abines meeting 009	Discussion	Cussion

